

Alibre Design Exercise Manual

Introduction to Sheet Metal Design





Copyrights



Information in this document is subject to change without notice. The software described in this documents is furnished under a license agreement or nondisclosure agreement. The software may be used or copied only in accordance with the terms of those agreements. No part of this publication may be reproduced, stored in a retrieval system, or transmitted in any form or any means electronic or mechanical, including photocopying and recording for any purpose other than the purchaser's personal use without the written permission of Alibre, LLC.

Alibre, LLC
1750 N Collins Blvd
Ste. 212
Richardson, TX 75080
U.S.A

www.alibre.com

© 2018 Alibre, LLC. All rights reserved.

Alibre and the Alibre logo are registered trademarks in the United States and/or other countries.




Creating a Tool Holder

This lesson will take approximately 30 minutes to complete.


You will learn:

- How to create, edit, and dimension sketch figures.
- How to produce base Sheetmetal features like Tabs and Flanges.
- How to add standard versus miter flanges.
- How to use the Linear Feature Pattern tool.
- How to use the Cut and Dimple Sheetmetal tools.
- How to add Color Properties to your part
- How to Unbend, Rebend, and Flat Pattern your Sheetmetal part.







1. Open a new **Sheet Metal Part** workspace from Alibre Design's **Home** window.




1. Click on the **File** tab.
2. Go to **Properties**.
3. Go to **Units>General** and select **Centimeters** from the dropdown.




1. Click on the **Sheet Metal** tab in the ribbon, if necessary.
2. Click on the **Activate 2D Sketch** icon.
3. Click on the **XY Plane** in the **Design Explorer** or the **Work Area**.




1. Select the **Grid** options.




1. Enable the **Display Grid** option if it is unchecked.
2. If necessary, change the values to 1.27cm for X, Y, and Z.
3. Press the **OK** button.




1. Make sure **Real Time Dimensioning** is turned on.




1. Click on the dropdown menu of **Rectangle** tool on the **Sketch Figures** tab in the ribbon.
2. Select the **Rectangle by Center** from the List.




1. Position the mouse cursor near the **Origin** point. Roll the mouse wheel forward to zoom in. The view of the work area should be like the screen capture.
2. Position the mouse cursor over the **Origin** point. The point's color and cursor tool tip changes confirm that the mouse cursor is positioned properly. *Click and Release* to create the center point of the Rectangle.




1. Move the mouse cursor horizontally to the right, input a dimension of **3.81cm** for the horizontal distance from the center of the rectangle to its edge, and then hit **Tab**.
2. Enter the value of **7.62cm** vertical distance from the center of the rectangle to the bottom and press **Enter**.




1. Click on **Dimension**.
2. Select the left or right vertical line of Rectangle, then click on the workspace location where you want to place the dimension and confirm the value of **15.24cm** and press **Enter**.
3. Select the bottom line of the Rectangle and click on the workspace location to place the dimension and confirm the value is **7.62cm** and click the **Green Checkmark** or press **Enter**.




1. Completed rectangle view of the work area should be like the image above.




1. Click on the dropdown menu of **Circular Arc** tool on the **Sketch Figures** tab in the ribbon.
2. Select the **Circular Arc-Start, End, Radius** option from the List.




1. Move the mouse cursor over the top-left sketch node on the rectangular sketch (**3.81cm to the left of the origin & 7.62cm above the Origin**). *Click and release* to create the Start point of the Arc.
2. Move the mouse cursor over the top-right sketch node on the rectangular sketch. *Click and release* to create the End point of the Arc.
3. Move the mouse cursor in an upward direction until the tangential constraint symbols appear. *Click and release* to complete the Arc.




1. Click on the **Trim** tool on the **Sketch Tools** tab in the ribbon.
2. Click on the top horizontal sketch line to execute the **Trim**.




1. Click **Yes** on the pop-up window to complete the process.




1. Use the **Equal Constraint** for the two long sides of the rectangle so they will remain the same length.
2. Use the Dimension tool to apply a **7.62 cm** dimension between the **Center Point** of the arc and the **Origin**.
3. Completed Sketch view of the work area should be similar to the screen capture.




1. Click on the **Circle** tool on the **Sketch Figures** tab in the ribbon.
2. Move the mouse cursor close to the position shown (**10.06cm over the Origin**). *Click and release* to create the Center point of the **Circle**.
3. Enter a value of **.635cm** for the circle's diameter, and then hit **Enter** on your keyboard to apply the value.




1. Click on **Dimension**.
2. Click on the **Center Point** of the circular sketch you just created.
3. Click on the **node point** referenced by Callout “3” in the image above.
4. Enter a dimension of **2.54cm**, hit **Enter**, and click **Deactivate Sketch**.




1. Click on the **Tab** in **Base Features** section in the ribbon.
2. Confirm that **Sketch<1>** appears in the **Tab**; entry box.
3. Click **OK**.




1. Confirm similar results for the **Tab** operation.




1. Right-click on the Front Face of the Tab and click **Activate 2D Sketch**. Alternatively, you can click on the front face and press **Ctrl+K**.




1. Use the **Rectangle** sketch tool to create a rectangular sketch similar to what is shown above.
2. Use the **Dimension** tool and apply a width of **0.508cm** and a length of **5.08cm** to the rectangular sketch.




1. Zoom in if needed (not shown).
2. Use the **Dimension** tool to center the rectangular sketch. Use a value of **1.27cm** for the distance from the left edge of the tab. You will see a reference line appear.
3. Use the **Dimension** tool and apply a **2.286cm** distance from the top horizontal line of the rectangular sketch to the top node point of the reference line.




1. Use the **Circular Arc – Start, End, Radius** sketch tool to create two arcs at each end of the rectangle with a radius of **.254cm**
2. Use the **Trim** tool to remove the vertical sketch lines of the rectangle, creating an obround shape as shown above.




1. Click on the **Sheet Metal** tab.
2. Click on the **Cut** tool in the **Sheet Metal Tools** section of the Ribbon,
3. In the dialog, select **Sketch<2>**, make sure the cut type is **To Depth** and the depth is set to **AD_Thickness**.
4. Click **Ok**.




1. Click the **Linear Feature Pattern** tool.
2. In the **Linear Feature Pattern** dialog box, click on the **Features to pattern** field.
3. Select **Cut<2>**.




1. In the **Linear Feature Pattern** dialog box, click on the box named **Linear Path** and select the highlighted edge as the **Pattern Direction**.
2. Click the **Change Direction** checkbox.
3. Set the **Spacing** to **1.27 cm** and the **Instances** to **9**.
4. Click **Ok**.




1. Confirm the results of the **Feature Pattern**.
2. From the **Quick Access** bar, click the dropdown for **Isometric Views** and select **Isometric (+X,+Y,+Z) View**.




1. Click on the **Flange** in **Sheet Metal Tools** section in the ribbon.
2. Click the **Edge** box inside the Dialog.
3. Click on the edges shown to select them.




1. Set the length value for the **Flange** to **3.81 cm**.
2. Select the **Adjacent** option under **Alignment** in **Main** tab of **Flange** dialog box.
3. Select the **Tab** under the **Length** option in **Main** tab of **Flange** dialog box.




1. Click on the **Corners** tab in the **Flange** dialog box.
2. Click on the checkbox and Enable the **Miter**.
3. Select the **Corner Closed** under the **Miter** in **Corners** tab of **Flange** dialog box.
4. Input a value of **.02032** for the **Gap width**
5. Click **Apply**.




1. Confirm similar results for the **Flange** operation.
2. Click on the **Close**.




1. Click on **Flange** in **Sheet Metal Tools** section in the ribbon.
2. Click on the **Edge** box in the dialog.
3. Position the mouse cursor over the inside edge of the left flange, and then click to select it.




1. Select the **Inside** option under **Alignment** in **Main** tab of **Flange** dialog box.
2. Enter a value of **7.62 cm** for the leg length in the dialog.
3. Select the **Tab** under **Length** in the **Main** tab of **Flange** dialog box.
4. Click **Apply** then **Close**.




1. Confirm similar results for the **Flange** operation.




1. Select **Bottom View** icon from the **Quick Access** toolbar.
2. Click on **Flange** in **Sheet Metal Tools** section in the ribbon.
3. Click the **Edge** box in the dialog.
4. Click on all four inside edges of the bottom of the sheet metal part
5. Set the length value to **1.89 cm**




1. Click on the **Corners** tab in the **Flange** dialog box.
2. Click on the checkbox and Enable the **Miter**.
3. Select **Corner Relief** under **Miter** in the **Corners** tab of **Flange** dialog box.
4. Confirm the **Gap width** value in the **Flange** dialog box is **.02032**.
5. Click **OK**.




1. Click the **Front View** icon in the **Quick Access** toolbar.
2. Right-click on the front face of the sheet metal part.
3. Select the **Activate 2D Sketch** from the Menu or Press **Ctrl+K** on Keyboard.




1. Click on the **Project to Sketch** tool and then click on the top edge of the front face of the model.
2. Choose the **Create reference figure** option in the dialog.
3. Click **OK**.




1. Click on the **Line** tool, then hover your cursor over the center point of the reference line.
2. Create the sketch lines as shown.




1. Use the **Circular Arc-Start, End, Radius** to create an arc with a radius of **1.5875 cm** to close the sketch.




1. Click on the **Mirror** tool and select the sketch lines you just created except for the vertical line, and populate the **Figures to Mirror** box of the Mirror dialog.
2. Click on the **Mirror Axis** box of the mirror figure dialog.
3. Select the vertical line of the sketch for the **Mirror axis** field in the dialog.
4. Click **OK**.




1. Use the **Trim** tool to remove the center line. Click **Deactivate Sketch** (Not shown).
2. Click on the **Cut** tool in the **Sheet Metal Tools** section on the Ribbon.
3. Select the **To Depth** option from the dropdown menu of **Type** in the **Cut** Dialog Box.
4. Click **OK**.




1. Confirm similar results for the **Cut** operation.
2. Right-click on the front face of the part and select the **Activate 2D Sketch** from the Menu or Press **Ctrl+K** on Keyboard.




1. Select the **Rectangle** tool in the **Sketch Figures** section on the Ribbon.
2. Sketch a rectangle with a **Length** of 5.08cm and a **Width** 1.27cm.
3. Use the **Dimension** tool to enter 2.54cm between the top of the rectangle and the bottom edge of the part, and 1.27cm between the left side of the rectangle and the left edge of the part.
4. Click **Deactivate Sketch**.




1. Click on the **Dimple** tool in **Sheet Metal Tools** section in the Ribbon.
2. Confirm that the sketch you just created appears in the Sketch field of the Dimple dialog.
3. Input a **1 degree** draft angle in the **Draft angle** field of the dimple dialog.
4. Enable the Checkbox named **Cut Out Material**.
5. Click **OK**.




1. Click the **Part Color** button in the **Sheet Metal Tools** section of the Ribbon.




1. Click on **Color** in the **Color Properties** dialog.
2. Select a bright orange color in the **Color** dialog box by clicking on one of the colored tiles in the **Basic colors** area.
3. Click **OK** in the **Color** dialog box.
4. Click **OK** in the **Color Properties** dialog box.




1. Confirm similar results for the **Color Properties** operation.




1. Click the **Unbend** tool and select the back face of the part as the **Fixed Face**.
2. Click on the **Select All Bends** option.
3. Click **OK**.




1. Confirm the results of the **Unbend** tool.
2. Blue color lines show the Bending Pattern.
*Notice that the Pattern represents the bends as it would on the physical object.




1. Click on the **Rebend** tool.
2. Click **Select all unbent bends**, and click **OK**.




1. Confirm the results of the **Rebend**.



1. Click on the **Flat Pattern** in the **Sheet Metal Tools** tab in the **Ribbon**.



1. Confirm similar results for the **Flat Pattern** operation.
2. Blue color lines show the Bending Pattern.
 - * Notice that the Pattern represents the bends as it would on the physical object.



1. Click **Flat Pattern** again to return the sheet metal part to its closed state.
2. Save this Sheet Metal file to your preferred location with the name: **Tool_Holder** (not shown).
3. Close the **Sheet Metal** workspace (not shown).

This concludes the Tutorial.